

EasyCUT

Static Remover for Microtomes

REMOVE STATIC CHARGES FROM ANY PARAFFIN BLOCK PROCESSED

During paraffin block cutting, electrostatic charges may often occur. These charges make ribboning difficult, as the sections stick to the paraffin block itself, to forceps and to user's fingers. Transferring to the water bath is almost impossible and section ribbons may break apart. We offer you a solution to this problem.



